




Komplet naprawczy tylnego zacisku hamulcowego japońskiego producenta Tourmax:



Honda XL600V Transalp

Numer OEM Honda wg schematu:

2 - 06451-443-405
 12 - 43132-KT7-761
 15 - 43353-461-771
 17 - 45133-MA3-006

Zastosowanie:

HONDA:

CB600 Hornet 98-15
 CB750 Seven Fifty 92-03
 CB900 Hornet 02-06
 CB1000 93-96
 CB1300 03-13
 CB-1 400 89-90
 CBF500 04-08
 CBF600 04-13
 CBF1000 06-14
 CBR600 91-13
 CBR900 92-03
 CBR1000 04-05
 FMX650 05-07
 NC700 12-14
 NSA700 08-11

NT650 Deauville 88-01
NTV650 Revere 88-97
NX650 Dominator 88-96
VT1100 Shadow 95-00
VTR250 09-11
VTR1000 Fire Storm 97-06
VTX1300 03-07
XL600V Transalp 91-00
XL650V Transalp 00-07
XL700V Transalp 08-13
XRV650 Africa Twin 88-90
XRV750 Africa Twin 90-03
Kawasaki:
Z750 07-14
ZX-7RR Ninja 96-99
ZZR1400 06-12

ID: 394
Tourmax BCR-113